




PRODUCT

CHANGE NOTIFCATION



Multiple Relay Series (Partial) - DISCONTINUATION

Due to diminishing global demand, Omron will discontinue select part numbers within Multiple Relay Series, in an effort to streamline our product offering and focus on popular models of Omron's line of Relays. Omron will discontinue those relays at the end of February 2024. The following notice will explain the discontinuation and suggested replacement considerations, if any exist. Should you have any additional questions please communicate with your local OMRON Sales Professional.

Note: Sales history of these discontinued items is extremely limited over the past several years; the number of affected customers will be minimal. The family series the part numbers belong to are not being discontinued.

Last Time Buy Date:

February 29, 2024

Details of Discontinued Models:

Discontinued Model	Suggested Replacement
G2R-2-AUL-T130 DC24 BY OMI	No Suggested Replacement
G2R-2-T130-WR DC24 BY OMI	No Suggested Replacement
G2RL-1-CF DC5 BY OMB	G2RL-1 DC5 BY OMB
G2RL-2A-CF DC12 BY OMB	G2RL-2A DC12 BY OMB
G3VM-401EY(TR)#S	No Suggested Replacement
G3VM-41LR5(TR05)#S	No Suggested Replacement
G5LE-1 DC24 BY OMB (JB)	No Suggested Replacement
G5LE-1-ASI-60 DC24 BY OMB	No Suggested Replacement
G5LE-1-CF DC12 BY OMB (ELUX)	No Suggested Replacement
G5LE-14 DC12 BY OMB (CI)	No Suggested Replacement
G5LE-14 DC12 BY OMB (JB)	No Suggested Replacement
G5LE-14 DC24 BY OMB (IV-P)	No Suggested Replacement
G5LE-14 DC9 BY OMB (IV-P)	No Suggested Replacement
G5LE-14-CF DC24 BY OMB (WH)	No Suggested Replacement
G5LE-1A DC24 BY OMB (JB)	No Suggested Replacement
G5LE-1A4 DC18 BY OMB (IV-P)	No Suggested Replacement
G5LE-1A4 DC24 BY OMB (IV-P)	No Suggested Replacement
G6A-234P-ST1-US DC5	No Suggested Replacement
G6A-234P-ST10-US DC48	No Suggested Replacement
G6A-234P-ST10-US DC9	No Suggested Replacement
G6A-274P-ST58-US DC24	No Suggested Replacement
G6AK2-UA 006341	No Suggested Replacement
G6AK2-UA 006342	No Suggested Replacement
G6AK2-UA-006337	No Suggested Replacement
G6AK2-UA-006339 DC48	No Suggested Replacement
G6AK2-UA-006340 DC5	No Suggested Replacement
G6AK2-UA-006400 DC5	No Suggested Replacement
G6AK2-UA-006401 DC12	No Suggested Replacement
G6AK2-UA-006402 DC24	No Suggested Replacement
G6AU-2-H DC12	No Suggested Replacement
G6AU-2-H DC48	No Suggested Replacement
G6AU-2-H DC5	No Suggested Replacement
G6AU-2-H DC9	No Suggested Replacement
G6AU-2-L DC12	No Suggested Replacement
G6C-1114P-VD DC12	No Suggested Replacement
G6C-2114C-US-6000 DC24	No Suggested Replacement
G6C-UA-006003 DC5	No Suggested Replacement
G6C-UA-006005 DC12	No Suggested Replacement
G6C-UA-006006 DC24	No Suggested Replacement
G6D-1A-ASI-UA-006003 DC24BYOMB	No Suggested Replacement
G6EK-134P-ST-1-US DC3	No Suggested Replacement
G6EU-134P-ST-US DC24	No Suggested Replacement
G6EU-134P-ST-US DC3	No Suggested Replacement
G6EU-134P-ST-US DC9	No Suggested Replacement
G6EU-134PL-ST-US DC5	No Suggested Replacement
G6KU-2F-RF-S-TK DC3	No Suggested Replacement
G6KU-2F-RF-S-TK-TR03 DC3	No Suggested Replacement
G6KU-2F-RF-S-TK-TR09 DC3	No Suggested Replacement
G6KU-2F-Y-TR DC3 ADC	No Suggested Replacement
G7L-1A-P-CB-DC DC12 BY OMI	No Suggested Replacement
G7L-1A-T-CB-BS AC100/120 BYOMI	No Suggested Replacement
G7L-2A-BUBJ-80-CB DC24 BY OMI	No Suggested Replacement
G7L-2A-TUBJ-CB-RBI AC100/120BY	No Suggested Replacement

** Sales teams should communicate this discontinuation with their OEM's and CEM's.
For further technical support and any questions, please communicate with Product Marketing*

MULTIPLE RELAY SERIES (Partial) - DISCONTINUATION

Thank you,
OMRON Product Management Team

